

To: Jessie Graham[jgraham@pgei.com]
Cc: Mike Hackney[mhackney@pgei.com]; Gallant, William[Gallant.William@epa.gov]
From: Suchomel, Bruce
Sent: Wed 9/23/2015 3:15:04 PM
Subject: RE: Section 36 Lat/Long

Jessie,

I appreciate you sending these maps. We actually need the exact coordinates and exact footage calls – thanks.

Bruce Suchomel
UIC Program - Environmental Engineer/Project Manager
USEPA Region 8 (P-W-UIC)
1595 Wynkoop St.
Denver, CO 80202-1129
303-312-6001

From: Jessie Graham [mailto:jgraham@pgei.com]
Sent: Tuesday, September 22, 2015 2:42 PM
To: Suchomel, Bruce
Cc: Mike Hackney; Gallant, William
Subject: Section 36 Lat/Long

Bruce,

I have attached two documents, the first is a survey plat showing section 36 in T5S-R4W is slightly irregular, it is not a perfect mile by mile square. I added the footage that the East Quarter section should be at to the plat in red text—this was done by me NOT the surveyors.

The second document, a map I have been working on, shows the approximate Lat/Long values of the corners. The coordinates are in NAD27, Zone 12, survey feet.

If you want more precise values, we will need to contact our surveyor to get those, please let me know what you need. I can update the map and remove the “DRAFT” status on it once we know

about how precise you want the coordinates.

Jessie Graham

Petroglyph Energy, Inc.

O:208-685-7631

C:208-861-3734

The contents of this e-mail and any attachments are intended solely for the use of the named addressee(s) and may contain confidential and/or privileged information. Any unauthorized use, copying, disclosure, or distribution of the contents of this e-mail or attachments is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender immediately and destroy all copies of the communication and any attachments.